


ACCUMARK

Subsurface Utility Services

Utility Test Hole Report - Quality Level "A"

Test Hole #: <u>8</u>	Project Numbers: <u>09-442</u>
Project Name: <u>Route 623</u>	Project Location: <u>Anywhere, USA</u>
Requested By: <u>Smith Engineering</u>	Work Type: <u>Infrastructure</u>
Point of Contact: <u>John Smith</u>	Improvements
Utility Requested: <u>Telephone</u>	Test Hole Date: <u>08-21-09</u>
Utility Found: <u>Telephone Duct</u>	Soil Conditions: <u>Moist Clay Rock</u>
Material Makeup: <u>Concrete Duck Bank</u>	Utility Condition: <u>Good</u>
Size Utility Found: <u>Duct</u>	Pavement Cond: <u>Good</u>
	<u>0.7' Asphalt</u>

<p style="text-align: center;">Test Hole Information:</p> <p>Elevation at hub & tack / Pk: 162.87' Existing grade depth @ top of utility: 4.12' Elevation at top of utility: 158.75' Elevation at bottom of utility: 156.84'</p> <div style="display: flex; align-items: center;"> <div style="margin-right: 20px;"> <p>Cover (Top): 4.12'</p> <p>Cover (Bottom): 6.03'</p> <p>Drawn Facing: East</p> </div>  <div style="margin-left: 20px;"> <p>Existing Grade</p> <p>Utility Width: N/A</p> </div> </div>	<p style="text-align: center;">Elevation / Survey Information:</p> <p>Located By: <u>Benchmark Elevation</u> Accumark, Inc. 166.74"</p> <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;"><u>Northing:</u></td> <td style="text-align: center;"><u>Easting:</u></td> <td style="text-align: center;"><u>Elevation:</u></td> </tr> <tr> <td style="text-align: center;">6994371.924</td> <td style="text-align: center;">11784396.304</td> <td style="text-align: center;">162.87'</td> </tr> </table> <p>Notes:</p> <p>Pk set over North edge of duct.</p>	<u>Northing:</u>	<u>Easting:</u>	<u>Elevation:</u>	6994371.924	11784396.304	162.87'
<u>Northing:</u>	<u>Easting:</u>	<u>Elevation:</u>					
6994371.924	11784396.304	162.87'					

